



- New north and west parking lot were poured. Site cleanup in progress.
- Renovations are ongoing in classroom areas with paint and ceiling grid.
- Phase 2 addition mason is complete. Exterior metal panels to start in April.
- All exterior window frames and glass are installed. Temporary entry doors
- Installation of wall tile is ongoing in main corridors and restrooms.
- Roofing of the Phase 2 addition is complete.
- Overhead electrical, HVAC, plumbing, and fire sprinklers is 95% complete in Phase 2.
- HVAC equipment started and building has conditioned air.







Phase 2 Addition and Main Entry










Art Courtyard and Marquee








Auditorium Stage and Control Booth







Main Corridor and PLC Room







Band Hall & Standard Classroom







Art Classroom & Collaboration







Collaboration Area



LOWE & MCREAVY ELEMENTARY SCHOOLS

- Sidewalks are being poured and canopies are in progress.
- Metal wall panel and window installations are nearing completion.
- Storefront windows and doors are in being installed.
- Finishes are ongoing including wall tile, paint, and casework.
- Ceiling devices are being installed.
- Lights are being turned on.
- Basketball goals are being installed at the gyms.
- Food service equipment installations are ongoing.





LOWE ELEMENTARY



Front Entry and Canopy





LOWE ELEMENTARY



Classroom wing exterior and Science lab canopy



LOWE ELEMENTARY



Gym/Cafeteria

LOWE ELEMENTARY




Wall tile in progress

LOWE ELEMENTARY



Classroom corridors





MCREAVY ELEMENTARY



Front Entry




MCREAVY ELEMENTARY



Exterior Paving

MCREAVY ELEMENTARY



Wall Tile Progress

MCREAVY ELEMENTARY



Classroom Corridors



MCREAVY ELEMENTARY



Media Center



MCREAVY ELEMENTARY



Administration

DESIGN DEVELOPMENT OVERALL LEVEL ONE THE LOUNGE


EDUCATION SERVICES CENTED

BOND 2 EDUCATION SERVICE CENTER

- Sitework has started on the ESC-Transportation-Ag-Elementary #8 project.
- Detention pond is 95% complete.
- Site fence, silt fence, and tree protection installed.
- Pier drilling has begun.
- Ag Science Metal Building has been ordered.
- Stewart Builders jobsite office trailer is completed.



BOND 2 EDUCATION SERVICE CENTER



Site Layout






ESC-Ag-Elementary #8



Aerial View - Looking Southeast



ESC-Ag-Elementary #8




Aerial View - Looking Southwest





ESC-Ag-Elementary #8



Aerial Drone Video



